















Náradie pre prácu pod napätím do 1000V



TYP SADY		5570EN	5571EN
Obrázok	Náradie v sade	5.0251280	5.0251285
	Obal	●	●
	293N-160	●	●
	401N-160	●	●
	322N-160		●
	451N-160	●	●



TYP SADY		F3-1000V	F4-1000V	F3C-1000V	F4C-1000V
Obrázok	Náradie v sade	5.0251290	5.0251295	5.0251300	5.0251305
		●	●	●	●
	F20-160	●	●		
	F10-165	●	●		
	F80-160	●	●		
	F60-160		●		
	F100-190			●	●
	F200-160			●	●
	F800-160			●	●
	F600-160				●